

$\varnothing 80 \pm 0.2$

4XM6 EQS
 $\nabla 12$ (螺纹)

$2 \times \varnothing 6^{+0.012}_0$
 $\nabla 7$

40 ± 0.02

40 ± 0.02

18

$\varnothing 90^{+0.005}_{-0.035}$

